

# Navajo Abandoned Uranium Mine Site Screen Report

*This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits and pits. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites lands not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands but that are or may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.*

*The purpose of the form is to ascertain the status and location of the identified AUM site, to record all immediate site information associated with the mine site and to document the recommendation and/or decision on what additional steps, if any, are needed at the site.*

## **Dakota AUM Site**

## **Navajo AUM Eastern Region**

### **Prepared by:**

**Weston Solutions, Inc.**

**Contract: W91238-06-F-0083**

**12767.063.496.1111**

**May 2009**

**Part I Site Identification, Location and Status****Site Names and ID numbers as applicable****Mine ID:** 348**Map ID:** E75**CERCLIS:** NNN 000 908 706**NAMLRP:** NOT ASSIGNED**New Mexico Mining and Mineral Division ID:** NM00154**New Mexico Bureau of Geology and Mineral Resources:** NMMK0041**Local name / Aliases:** N/A**Chapter and local area:** Baca/Haystack Chapter**Lat/Long:** 35.3851223123 N / -107.896091535 W**Nearby road and highway:** Blackwood Road, BIA 41 (Red Mountain Road)**Local Post Office:** Prewitt, NM**Land Status: check one or more and provide ownership and contact information below**

<b>Tribal Trust Land</b>	<input type="checkbox"/>
<b>Tribal Fee Land</b>	<input type="checkbox"/>
<b>Allotment</b>	<input checked="" type="checkbox"/>
<b>Fee land</b>	<input type="checkbox"/>
<b>Public lands</b>	<input type="checkbox"/>
<b>Private</b>	<input type="checkbox"/>
<b>Bureau of Land Mgmt</b>	<input type="checkbox"/>
<b>State</b>	<input type="checkbox"/>

**Ownership and contact information:**

No ownership was identified. The mine site property is classified as Allotment land, but no residences were found within 0.25 miles of the site

## **Part II            Site Observations**

**Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:**

**0 to 200 feet:** None                      **200 feet to 0.25 mile:** None

**Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:**

**0 to 200 feet:** None                      **200 feet to 0.25 mile:** None

**Levels measured around the perimeter(s) of the identified structure(s):**

None

**Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:**

**0 to 0.25 miles:** None                      **0.25 miles to 4 miles:** unk

**Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.**

None observed

**Known Site History: include information from interviews with Chapter officials and residents.**

**Note information on mine ownership, period of operation, and type of mining operation.**

The Dakota mine consists of a surface area of 9,564.20 square meters and underground workings of unknown extent. Any historical information pertaining to mining operations and historical ownership of the mine site appeared to be unclear. The New Mexico Mining and Minerals Division identified the operator from 1952-1959 as the Dakota Mining Co.; 1959 Black Rock Mining Co., Inc.; and 1962 -1963 Farris Mines, Inc.

**Part III      Type, number and reclamation status of mine features**

**Provide description and reclamation status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all reclamation caps.**

Reclamation status of the mine sites are currently unknown. No visible signs of reclamation were observed. Three adits are located in hillside with waste rock material extending from adits to drainages below the mine. No other mine features were observed during the site visit.

**Part IV      Summary of radiological readings****Background Locations**

#1 13,000 cpm

**Mine site: Dakota**

- See Figures 1 and 2

**Nearby Structure Perimeter** – None

**Describe any other radiological measurements:**

A total of 1,178 gamma radiation measurements were collected from the mine site, ranging from 9,810 cpm to 292,715 cpm. Gamma radiation measurements at the mine adits were as great as 650,000 cpm. The measurements are represented in Figures 1 and 2. The New Mexico Mining and Minerals Division identified radiological measurements with background levels 50 counts per second (cps); and a high of 500 cps.

**Part V            Site sketch of all mine features and readings, including locations of all structures, sources of drinking water and any other important features and radiological readings.**

Presented in Figures 1 and 2

## **Part VI        Response Action Summary**

**Site Name(s):** Dakota        **Chapter:** Baca/Haystack

### **Decision Criteria**

**Is there an unreclaimed waste pile at the site?** Yes

**At what distance from the waste pile is the nearest residential structure located?** 1.4 miles

**At what distances from the waste pile are there potential drinking water sources?** 1.4 miles

**Is there a reclamation cap or sealed adit in place at the site?** No

**Is the cap/seal functionally intact?** N/A

**Is the cap/seal sufficiently degraded to create a concern about releases?** N/A

**At what distance from the cap/seal is the nearest domestic structure located?** N/A

**At what distance from the cap/seal is the nearest domestic drinking water source?** N/A

### **Summary of emergency response factors**

None

### **Summary hazard ranking system factors**

None

### **Summary of reclamation factors**

No known reclamation

## Part VII      Photos



Photo 1. Dakota Mine site, towards the north



Photo 2. Dakota Mine site, adit in hillside



Photo 3. Dakota Mine site, adit in hillside



Photo 4. Dakota Mine site, adit in hillside



**Part VIII      Contacts Reports and Information**Name Stanley EdisonTitle or official role (if any) Navajo EPA Superfund ProgramAddress PO Box 2946, Window Rock, AZ 86515Telephone number (928) 871-6861Information provided General Background and Contact/Access Information

---

Name Susan A. Lucas KamatTitle or official role (if any) AUM Data Manager – New Mexico Mining & Mineral DivisionTelephone number (505) 476-3408 fx: (505) 476-3408Information provided Background information and findings from 2008 New Mexico MMD  
Survey of mining sites.

---

Name Ms George PadillaTitle or official role (if any) Regional Environmental Scientist, BIA, Navajo NationTelephone number (505) 863-8434Address PO Box 1060, Gallup, NM 87305

---

Name \_\_\_\_\_

Title or official role (if any) \_\_\_\_\_

Telephone number \_\_\_\_\_

Information provided \_\_\_\_\_

---





